E.I. du Pont de Nemours and Company

Abstract:

5

Method of repairing defective areas in a stoving lacquer coating, in which the defective area ready for repair lacquering is coated with a powder coating composition or with an aqueous powder coating slurry, and the applied 10 powder coating is then melted and cured by irradiation with

0 powder coating is then melted and cured by irradiation with near infrared radiation (NIR).